

CORAIL HELICOTERES – Aéroport de Pierrefonds - 97410 Saint Pierre

☎ : +262 (0)6 92 00 66 66 – ✉ : fabricelourme@corailhelico.com



Total time since new 5721 hours

Availability Immediate

Production year 2004

Status In operation

| Next visit | Hours date | Time Remaining |
|-------------|-----------------------|-------------------|
| 600h / 24M | 6295h10 27/11/2021 | 572h12 1Y 8M |
| 1200h / 48M | 6916h17 23/01/2024 | 1193h19 3Y 10M |
| 144M | 20/08/2021 | 1Y 5M (+6M) |

Aircraft availability subject to prior sale. Components remaining times, configuration and equipment subject to buyer's verification prior to purchase

- Optional Equipment List

General Equipment

| | | |
|----------------|---|---|
| 05-03002-00-CI | First aid kit | 1 |
| 05-23002-00-CI | Engines flushing device without removal of cowlings | 1 |
| 05-24003-00-CI | High visibility main rotor blades | 1 |
| 05-24004-00-CI | Tail rotor arch | 1 |
| 05-32001-00-CI | Pilot's windshield wiper | 1 |
| 05-32003-00-CI | Copilot's windshield wiper | 1 |
| 05-37008-00-CI | Dual controls | 1 |
| 05-61007-03-CI | 2nd battery kit | 1 |
| 05-93001-00-CI | Mooring kit (ground or ships) | 1 |

Specific Mission Equipment

| | | |
|----------------|--|---|
| 06-11017-00-CI | Skid wearing plates | 1 |
| 06-12015-01-CI | High skid landing gear with 2 long footsteps | 1 |
| 06-21002-00-FP | Air Equipement electrical hoist (136 kg - 300 lb) - Fixed Parts | 1 |
| 06-26003-00-CI | RH side external mirror | 1 |
| 06-42006-00-CI | RH landing light (swivelling in elevation) | 1 |
| 06-61004-00-FP | Emergency floatation gear - Fixed Parts | 1 |
| 06-61004-00-RP | Emergency floatation gear - Removable Parts | 1 |
| 06-27006-00-FP | Cargo swing with dynamometer (1,134 kg - 2,500 lb) - Fixed Parts | 1 |
| 06-27006-00-RP | Cargo swing with dynamometer (1,134 kg - 2,500 lb) - Removable Parts | 1 |

Interior Layout

| | | |
|----------------|---|---|
| 07-24004-00-FP | Left side two-place front bench seat (pilot on right side) - Fixed Parts | 1 |
| 07-24004-00-RP | Left side two-place front bench seat (pilot on right side) - Removable Parts. | 1 |
| 07-50002-01-CI | Improved side-visibility in RH large front door. | 1 |
| 07-50003-00-CI | Left rear sliding door. | 1 |
| 07-50006-00-CI | Sliding window, on rear LH sliding door. | 1 |

Avionics

| | | |
|------------------|--------------------------------|---|
| 08-18035-00-CI | David Clark H10-13H - Headset | 5 |
| 08-21008-02-CI | Thales AHV16 - Radio altimeter | 1 |
| 08-83024-01-CI | VEMD data download kit | 1 |
| 08-51019-02-CI | Stand-by gyro horizon | 1 |
| Helicom Products | Helisafe | 1 |

Intégration d'un tableau de bord de type AS 350 B3 en lieu et place de celui d'un AS 355 NP

- Components remainings times : In line with TTSN

- Update March 2020

| Airframe components | Time Remaining |
|-----------------------------|---------------------------|
| Main rotor blade | 14 278:22 Hrs |
| Main rotor blade | 14 278:22 Hrs |
| Main rotor blade | 14 278:22 Hrs |
| Starflex | 2641:15 Hrs |
| Upper sleeve flanges | 5265:14 Hrs |
| Lower sleeve flanges | 5265:14 Hrs |
| Spherical thrust bearing(3) | 3654:21 Hrs |
| Main rotor mast | 14278:22 Hrs 61744 Cyc |
| MGB Bevel gear | 345:55 Hrs |
| MGB Epicyclic gear | 476:38 Hrs |

| Airframe components | Time Remaining |
|--------------------------|----------------|
| MGB Oil pump | 2654:05 Hrs |
| Coupling Unit | 2154:05 Hrs |
| Tail gear box | 168:58 Hrs |
| Tail rotor blade | 2271:04 Hrs |
| Starter generator | 566:19 Hrs |
| Starter generator | 1194:39 Hrs |
| Main servo control | 349:54 Hrs |
| Main servo control | 349:54 Hrs |
| Main servo control Front | 349:54 Hrs |
| Tail servo control | 349:54 Hrs |

| Engines ARRIUS 1A 1 | |
|--|-----------------------|
| SN 3039 | |
| Components | Time Remaining |
| Module 01 | 1507:02 Hrs 13Y |
| Module 02 | 1507:02 Hrs 13Y |
| SN 3008 | |
| Module 01 | 2916:41 Hrs 14Y 6M |
| Module 02 | 2916:41 Hrs 14Y 6M |
| Possibility : SBH full contract | |

Aircraft availability subject to prior sale. Components remaining times, configuration and equipment subject to buyer's verification prior to purchase